47

DART AEROSPACE LTD	Work Order:	19536
Description: Long Step Assembly - High Skid, RH	Part Number:	704A 41 640 007
D350-591-212		
Dwg: D3070 Rev. A1	Qty:	10
PF 02.11.13		Page 1 of 2

Step	Location	Procedure	Bv	Date	Qty	٦
1	DC	Issue Traveller	118			$\frac{1}{2}$
		Dwg not required	14Y	03.08.27	10	
2	DC	Photocopy bluefile and type labels per PPP 704A 41 640 007	HA	04.03.12	10	1
3	GA \	Cut D2622-120C extrusion to 116.25" long as per Dwg D30\(\frac{1}{2}\text{D}\) using cutting table setup DT8185-2A Pick: Qty Part Number Description Batch 1 D2622-120C Extrusion	0			
4	C 4	Ensure wall thickness is 0.070 to 0.090	130	04/03/03	10	
·	GA	Drill extrusion per Dwg D3070 using Jig DT8680 for rivets.	8B	04/03/03	10	
5	GA	Deburr	54			
6	QC5	Inspect work to Step 5	SK M	04/02/03	10	1
7	WA	Bevel end for welding FWD ONLY	141	04/03/03	10	-
8	WA		M	04/03/03	10	
(3)	\ \	Weld Support using Jig DT8681, weld Fwd End Plate per QSI 004 & Dwg D3070 Pick: Qty Part Number Description Batch 1 D3063-1 Support B/9555 1 D3067-1 End Plate B/9558 A/R Aluminum Rod	M	OHB363	/o	
9	GA	Grind End Plate flush	SRI	4603/04	In	
10	QC9	Inspect weld and work to Step 9	10	Nin a	(O	l
11	FP	Chemical conversion coat as per QSI 005 4.1	1	04.03.0B	10	
12	GA \	Assemble Leg Assembly as per Dwg D3070 D3066-1 are done Pick: Oty Part Number Description Batch 1 D3065-041 Step Leg Assy 2 D3066-1 Spacer B19557 16 MS20600AD4W4 Rivet M13767	ril	04-03-15		
13	QC5	Inspect work to step 12	M	04/03/16	10	
14	WA	Bevel Aft end for welding	W	04/02/11	/0	
15	WA	Inspect for foreign object per QSI 024	W	14/02/11	.10	
16	WA	Weld Aft End Plate per QSI 004 & Dwg D3070 Pick: Qty Part Number Description Batch 1 D3067-1 End Plate B/9558 A/R Aluminum Rod M/3066	M	04/03/16	10	

BB04-03-2325 POSITIVE RECALL

SAUTH A.

JOS PER PER STATE OF THE PER STATE OF TH

RELEASED

STEP NCR 748 U. Constable Chiusillo 16

Dart Aerospace Ltd

Work Order:		<u></u>	WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Manuf / Design Mgr	Approval QC Inspector
			in the second se						
		.,,							
		•					2		

NCR #	748	704A 41 640 007	WORK C	ORDER NON	-CONFORM	MANCE			
DATE	STEP	Description of NC section A	Intial		ve Action tion B	Sign & Date	Verification Section C	Approval Design Mgr	Approval QC Inspector
04-03-12	11	The Step was not Homogene colour "Poor awality)	ml	Redo	step 11	m23/3	or 103) 16	04.03.16	مالاهالان
		•.							

PAR#:	2/4	Fault Category:	A.	DQA:	A.	_ Date:	04.03.29
			A		\\ \		110

NOTE: Date & initial all entries H:Admin-QA\ISO\forms\w/oncB.doc

DART AEROSPACE LTD	Work Order:	19536
Description: Long Step Assembly – High Skid, RH	Part Number:	704A 41 640 007
D350-591-212		
Dwg: D3070 Rev. A (Qty:	10
		Page 2 of 2

17	GA	Grind End Plate flush			
			3B	04/03/16	(0
18	QC9 & 5	Inspect work to Step 17 – Check dimension 140.56" from Dwg D3070		04/03/16	10
19	FP	Powder Coat Gloss White (Ref: 4.3.5.1) per QSI 005 4.3	1	U4. 03.22	0
20	FP	Wing Walk per Dwg D3070 and QSI 005 4.4 mi-weg-	2	04.63.22	10
21	QC3	Inspect Powder Coat and Wing Walk	M	610,23	
22	KP	Pick: Packing Kit	/ / /		<i></i>
64.03.25	P3079-041	Oty Part Number Description Batch 4 D2182B035 Rubber Cushion B30434 8 D2274 Radius Block B30307 2 D2856-400-720 Abrasion Strip B19LH5 2 D3064-1 Clamp B20133 1 D3079-041 Support Assy B30456 4 D3080-1 Clamp B19559 2 AN3-35A Bolt M13943/M12597 10 AN4-11A Bolt M13735/M1293 4 AN960JD10 Washer M13441 20 AN960JD416 Washer M13441 2 MS21042L3 Nut (or -3) M14019 10 MS21042L4 Nut (or -4) M13376/M13630	G	04/03/04	10
23	QC4	Inspect 100% Kit for Completeness on the W/O		of 03-25	10
. 24	PK	Package for shipping as per PPP 704A 41 640 007	CP	04/03/25	10
25	AC	129 7	5 4F	04-03-29	/ 6
26	DC	Close W/O 239.3 o Inspect Level 21	A	14,03.29	10

Rev	Date	Change	Revised By	Approved
Α	02.11.01	New issue	KJ RF	
Ai	03,01.14	110.71" WAS 110.56"; Dwg. Rev. 41	 	#
AZ	03-7.16	D3194-241 WAZ D3279-041 CHGOOZ	科	#

See Day of ANCEL HOSDING

DELEASED 02/11/02

Dart Aerospace Ltd

Work Order:		WC	ORK ORDER CHA	NGES	.,			
DATE	STEP	.,	RE CHANGE	В	y Date	Qty	Approval Manuf / Design Mgr	Approval QC Inspector
				<i>i</i> ,				
		. • .						
	,							
NCR		WO	RK ORDER NON	-CONFORMANC	E			
DATE	STEP	Description of NC section A	Corrective Action Section B			ication ction C	Approval Design Mgr	Approval QC Inspector

							:	
		DAD"	Fault Oath and		DOA:		Deter	
		PAR#:	Fault Category:		DQA:		Date:	

NOTE: Date & initial all entries H:Admin-QA\ISO\forms\w/oncB.doc

QA: N/C Closed: ____ Date:___

Job Costing Report

Dart Aerospace Ltd. Hawkesbury

02:05 pm

Actual Margin :

Aug 27, 2003

0.000%

Work Order No : 0019536

Project Name Department Code:

Project Name : *704A 41 640 007 Project For : WK347 Burden Flags : NNNNNN Work Order Type : Main WO Status : Open

Main WO Number Invoice State : Not Invoiced

House Part Number: *704A 41 640 007 Description: Heli-Access-Step, Long RH Invoice Date :

Invoice Number :

Manufactured : Yes Invoice Amount: 0.00

Amount Req'd : 10
Amount Done : 0
Start Date : 08-27-03 Order Entry No :

OE Value : 0.00

Est Finish Date : 11-28-03 Est Margin : 0.000% Act Finish Date :

Drawings Reqd : No Ok for Approval :

Approval Rec'd : \$0 Posted to Finished Goods

*	Estimated	Actual	Var. %	Posted	To Post
Motorial Cost			=======	=========	==========
Material Cost :	0.00	0.00	0.00	0.00	0.00
Engineering Hours :		0.00	0.00		
Engineering Cost :	0.00	0.00	0.00	0.00	0.00
Production Hours :	0.00	0.00	0.00		
Production Cost :	0.00	0.00	0.00	0.00	0.00
Testing Hours ::	0.00	0.00	0.00		
Testing Cost :	0.00	0.00	0.00	0.00	0.00
OverHead Hours :	0.00	0.00	0.00		
OverHead Cost :	0.00	0.00	0.00	0.00	0.00
SubContract Hours :	0.00	0.00	0.00		
SubContract :	0.00	0.00	0.00	0.00	0.00
Misc. Hours :	0.00	0.00	0.00		
Misc. :	0.00	0.00	0.00	0.00	0.00
	========	========	, ======		
Burden :	0.00	0.00	0.00		
	========	=======	======		
Total Cost : :	0.00	0.00	0.00		
Margin :	0.000	0.000			
Selling Cost :	0.00	0.00			

		Estimated	Actual
Labour Hrs/Amount I	Done :	0.00	0.00
Profits/(Loss)	:	0.00	0.00

÷				
			*.	
	*			
				* *